Oil Field Environmental Incident Summary

Responsible Party: ENDURO OPERATING, LLC **Well Operator:** ENDURO OPERATING, LLC

Well Name: SWSCU 30-23

Field Name: SOUTH WESTHOPE Well File #: 4651

Date Incident:8/17/2014Time Incident:14:00Facility ID Number:County:BOTTINEAUTwp: 162Rng: 79Sec: 30Qtr:

Location Description: Single well site

Submitted By: Bryan Pease Received By:

Contact Person: Bryan Pease

777 MAIN STREET

SUITE 800

FORT WORTH, TX 76102

General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:1 MileDistance Nearest Water Well:1 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: No Reported to NRC: No Spilled Units Recovered Units Followup Units

Oil 3 Barrels 3 Barrels 3 barrels

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 10/19/2015 Clean Up Concluded: 8/21/2014

Risk Evaluation:

none

Areal Extent:

ran into a slough on the west side of pumping unit 25 feet by 50 feet

Potential Environmental Impacts:

none

Action Taken or Planned:

sucked oil off top of water with hydro vac truck and cleaned up facility soil with skid steer. Build permanent dike around well site facility.

Wastes Disposal Location: oil went to our oil tanks and facility soil to Prairie Waste Disposal.

Agencies Involved:

Updates

Date: 8/19/2014 Status: Inspection

Author: Kangas, Kathleen

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

8/19/14 - 11:30 on location; met company representative. Confirmed that oil and some produced water brine entered the large slough surrounding two sides of the location. Three rows of absorbent booms surrounded the impacted area of the slough, from location across open water and into extensive cattail stand. This is a large slough extending from north of the location 1/2 mile to Hwy 5 on the south and 1/4 to 1/2 mile to the west of the location. Contaminated soil has been stockpiled on the side of the location, and according to the company representative, it will be sent to a licensed disposal as quickly as he can make arrangements. Oil floating on open water along the location edge will be burned off after receiving a waiver from NDDoH. Specific conductivity along the location ranged from 2.54 to 2.77 mS/cm, but 100 feet to north of location along lease road, slough water registered 972 uS/cm. Relayed this to company representative, then took chloride screen with test strip (low range) = 600 mg/L approximately (7.8 on numeric scale).

Company plans to construct containment dike around location and will advise when burn complete, contaminated stockpile removed, and dike constructed.

NDDoH PIO alerted to need for press release.

Date: 8/19/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release ran off location into nearby slough. Followup is necessary.

Date: 8/27/2014 Status: Inspection Author: Kangas, Kathleen

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Contaminated soil removed. One layer of soft boom still in place in slough. No sheen observed on water. Appears cleanup occurred.